





Pessure Gauge  
Alarm Lamp

Route though  
battery bay  
below

Firetrace  
bottle